

FIG.1A




FIG.1B




FIG.1C




FIG.2A




FIG.2B




FIG.2C






FIG.3




RELATION BETWEEN C DOPE CARRIER CONCENTRATIONS
AND CRYSTAL GROWTH TEMPERATURES

FIG.4




RELATION BETWEEN Zn DOPE CARRIER CONCENTRATIONS
AND CRYSTAL GROWTH TEMPERATURES

FIG.5




RELATION BETWEEN H₂Se DOPE CARRIER CONCENTRATIONS AND CRYSTAL GROWTH TEMPERATURES

FIG.6



RELATION BETWEEN SiH₄ DOPE CARRIER CONCENTRATIONS AND CRYSTAL GROWTH TEMPERATURES

FIG. 7



RELATION BETWEEN GeH₄ DOPE CARRIER CONCENTRATIONS
 AND CRYSTAL GROWTH TEMPERATURES